

# bosal

**Инструкция  
по монтажу тягово-цепного  
устройства шарового типа 4237 А  
для автомобилей  
Hyundai Santa Fe**

	2000-...
	2000
	75
	25.22



462800,

« - »

18

т. (35363) 7-05-06

факс (35363) 7-13-20

т. (495) 785-66-07

www.bosal-autoflex.ru

« - »:	(8182) 22-48-15
" - "	" 8(8442) 98-74-98
" - "	" 8(343) 379-39-89, 373-42-73
" - "	" 8(343) 26-88-308
" - "	" 8(3952) 710-194
" - "	" 8(495) 777-54-59
" - "	" 8(495)745-79-11
" - "	" 8(495) 788-95-97
" - "	" 8(495) 720-51-03
" - "	" 8(3532) 57-99-85
" - "	" 8-905-899-5012
" - "	" 8(383) 291-59-60
" - "	" 8(831) 279-53-24
" - "	" 8(3422) 98-27-20
" - "	" 8(342) 220-87-87
" - "	" 8-927-002-90-06
" - "	" 8(3462) 24-00-44
" - "	" 8(3842) 21-14-76
" - "	" 8-902-940-4151
" - "	" 8(3452) 32-22-12, 41-52-62
" - "	" 8-961-213-0278
" - "	" 8-917-347-1700
" - "	" 8(351) 269-44-75, 900-72-73
" - "	" 8(3512) 773-76-91


..... : .....

..... VIN .....

.....

.....

41.55-2005.



	1 .
	1 .
	1 .
	1 .
	1 .

	3 .
12 1,25 /	2 .
12 /	6 .
12 65 ( )	4 .
12	20 .
12 1,25 90	2 .
12 130	2 .
12 40	4 .
12 120	2 .
12 1,25 35	4 .
L = 78	2 .
	2 .
VH 0160	1 .
	1 .
	1 .
	1 .
190	1 .
	1 .
	1 .

