

bosal

**Инструкция
по монтажу тягово-сцепного
устройства шарового типа 6738 А
для автомобилей
Kia Carnival**

	2006 -...
	1500
	50
	25



« - - »:	" (8182) 22-48-15
"	" 8(8442) 98-74-98
"	" 8(343) 379-39-89, 373-42-73
"	" 8(343) 26-88-308
"	" 8(3952) 710-194
"	" 8(495) 777-54-59
"	" 8(495)745-79-11
"	" 8(495) 788-95-97
"	" 8(495) 720-51-03
"	" 8(3532) 57-99-85
"	" 8-905-899-5012
"	" 8(383) 291-59-60
"	" 8(831) 279-53-24
"	" 8(3422) 98-27-20
"	" 8(342) 220-87-87
"	" 8-927-002-90-06
"	" 8(3462) 24-00-44
"	" 8(3842) 21-14-76
"	" 8-902-940-4151
"	" 8(3452) 32-22-12, 41-52-62
"	" 8-961-213-0278
"	" 8-917-347-1700
"	" 8(351) 269-44-75, 900-72-73
"	" 8(3512) 773-76-91

462800, « - - »
18
: (35363) 7-05-06
/ : (35363) 7-13-20
(495) 785-66-07
www.bosal-autoflex.ru

..... :

..... VIN

.....

.....

1. (,).

2.

3.

4. 1000

90 / .


1. « - » 12

8.8.

2.

3.

41.55-2005.



2)

; 3)

: 1)

10	1,25	40	4
12	30		2
12	1,25	40	5
12	45		4
12	1,25	75	2
12			4
12	1,25		2
8	016		2
10	016		4
12	016		7
10			4
12			5
8			2
12			14
			3
			1
		190	1
VH 0186			1
			1
			1
			1
			1

	1
	1
	1
	1
	1
	1
	1




Схема обрезки кабеля

